## TEST REPORT



CLIENT:

Stone Marketing International

2095 Afton

Houston, TX 77055

Attn: Louis Chosed

Test Report No:

818104

Date:

December 19, 2006

SUBJECT:

Evaluation of material to CTIOA T-72

SAMPLE ID:

Four (4) samples identified by client as Sealed Basaltina, Unsealed Basaltina, Sealed Impala Black Granite, and Unsealed Impala Black Granite were received from client on 12/06/06 in good condition. The sealed Basaltina and Impala Black Granite were sealed with Dry Treat Products: two coats Stain-Proof and 1 coat Porcelain Sealer.

PROCEDURE:

The material was evaluated in accordance with CTIOA T-72. No revisions to this

report will be allowed after 90 days of the report date.

RESULTS:

On the following pages

DATES TESTED:

12/14/06

**CERTIFICATION:** 

The tests reported here were conducted under the continuous direct supervision of

SGS U.S. Testing Company Inc., Tulsa, OK.

SIGNED FOR AND ON BEHALF OF SGS U.S. TESTING COMPANY INC.

Scott Parkhurst

Hydro Mechanical Dept. Supervisor

Hydro Mechanical Dept. Manager

Page 1 of 3

This report is issued by SGS U.S. Testing Company Inc. under its General Conditions for Testing Services, as printed on reverse side. SGS U.S. Testing's responsibility under this report is limited to proven negligence and will in no case be more than the amount of the testing fees, Except by special arrangement, samples are not retained by SGS U.S. Testing for more than 30 days. The results shown on this test report refer only to the sample(s) tested unless otherwise stated, under the conditions agreed upon. Anyone relying on this report should understand all of the details of the engagement. Neither the name, seals, marks nor insignia of SGS U.S. Testing may be used in any advertising or promotional materials without the prior written approval of SGS U.S. Testing. The test report cannot be reproduced, except in full, without prior written permission of SGS U.S. Testing Company Inc.

SGS U.S. Testing Company Inc. | Consumer Services Division 1341 North 108th East Avenue, Tulsa, OK 74116 t (918) 437-8333 f (918) 437-8487 www.sgs.com

Client: Stone Marketing International Report No.: 818104



## Procedure and Results

Procedure:

The stain solution was applied to a clean dry tile and allowed to remain on the tile for a period of 4 hours. After 4 hours the tile was scrubbed with tap water and a nylon brush and

wiped dry. The tile was then allowed to air dry for a period of 24 hours.

Sample: Basaltina (Sealed)

| Stain Solution | Result          |
|----------------|-----------------|
| Ketchup        | O No Stain      |
| Coffee         | O – No Stain    |
| Formula 409    | O – No Stain    |
| Mustard        | L - Light Stain |
| Red Wine       | O - No Stain    |
| Soy Oil        | O – No Stain    |
| Wesson Oil     | O - No Stain    |

## Sample: Basaltina (Unsealed)

| Stain Solution | Result           |
|----------------|------------------|
| Ketchup        | L - Light Stain  |
| Coffee         | O – No Stain     |
| Formula 409    | O – No Stain     |
| Mustard        | H - Heavy Stain  |
| Red Wine       | M - Medium Stain |
| Soy Oil        | H - Heavy Stain  |
| Wesson Oil     | H - Heavy Stain  |

<sup>\*</sup>Note: The Sealed sample was subjected to additional cleaning with 8 parts water and 1 part Clorox bleach. This mixture completely cleaned the tile surface changing the L rating (Light Stain) to an O rating (No Stain).



Sample: Impala Black Granite (Sealed)

| Stain Solution | Result          |
|----------------|-----------------|
| Ketchup        | O - No Stain    |
| Coffee         | L - Light Stain |
| Formula 409    | O - No Stain    |
| Mustard        | L – Light Stain |
| Red Wine       | O – No Stain    |
| Soy Oil        | O - No Stain    |
| Wesson Oil     | M – No Stain    |

Sample: Impala Granite (Unsealed)

| Stain Solution | Result           |
|----------------|------------------|
| Ketchup        | L – Light Stain  |
| Coffee         | O – No Stain     |
| Formula 409    | O - No Stain     |
| Mustard        | H - Heavy Stain  |
| Red Wine       | M – Medium Stain |
| Soy Oil        | H - Heavy Stain  |
| Wesson Oil     | H - Heavy Stain  |

\*Note: The Sealed sample was subjected to additional cleaning with 8 parts water and 1 part Clorox bleach. This mixture cleaned the tile surface changing the L rating (Light Stain) to an O rating (No Stain) and changed the M rating (Medium Stain) to an L rating (Light Stain).

\*\*\*

**End of Report** 

Page 3 of 3